

APPENDIX C

EMERGENCY ACTION PLAN

EMERGENCY ACTION PLAN

FOR

COWPATH DAM AND SULLIVAN DAM

SHELBY, MONTANA

Owner-Operator: City of Shelby, Montana
112 1st St S
Shelby MT 59474

Mayor: Gary McDermott

Engineers: Triple Tree Engineering
PO Box 162
Helena, MT 59624

Updated: September 24, 2021

If Cowpath Dam or Sullivan Dam is failing or failure seems imminent, call:

All Emergency Services 911/434-5585

Toole County Disaster and Emergency Services (24 hours)
Kelsey Buckley, Coordinator Home . 450-8013

Jack Johannes, City Superintendent . . . City Shop . 434-5564
Cell . 304-1307

TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION	
PURPOSE	1
DESCRIPTION OF DAMS	1
ACCESS TO DAMS	1
HAZARD AREA	1
RESPONSIBILITY AND AUTHORITY	3
PERIODIC REVIEW/UPDATE	3
APPROVAL	3
NOTIFICATION PROCEDURES	
IMMINENT OR ACTUAL FAILURE	4
POTENTIALLY HAZARDOUS SITUATION	6
POSTING OF THE NOTIFICATION FLOWCART AND DISTRIBUTION OF THE EMERGENCY ACTION PLAN	6
MITIGATION ACTIONS	
POTENTIAL PROBLEMS AND IMMEDIATE RESPONSE ACTIONS	8
EMERGENCY SUPPLIES AND RESOURCES	8
LOCAL CONTRACTORS	8
ENGINEERS	8
APPENDICES	
Appendix A - Technical Data for Cowpath Dam and Sullivan Dam	
Appendix B - Inundation and Evacuation Map	
Appendix C - Telephone Directory	
Appendix D - Dam Incident Report Form	
Appendix E - Potential Problems, Causes, Consequences And Action	
FIGURES	
Figure 1 Vicinity Map	2
Figure 2 Actual or Imminent Failure Notification Flowchart	5
Figure 3 Potentially Hazardous Situation Notification Flowchart	7

INTRODUCTION

Purpose

The purpose of this emergency action plan (EAP) is primarily to safeguard the lives of secondarily to reduce property damage to the citizens of Shelby in the event of flooding caused by a failure of Sullivan Dam or Cowpath Dam.

Description of Dams


The Cowpath Dam/Sullivan Dam facility is located in the south 1/2 of Section 15, and the north 1/2 of Section 22, Township 32 North (T32N), Range 2 West (2W), Toole County, Montana. The dams are located on an unnamed tributary to the Marias River. The facility is owned by the City of Shelby and is used as a flood protection, recreation, and fish and wildlife storage facility. Technical data pertaining to the Cowpath Dam/Sullivan Dam facility are listed in Appendix A. The locations of the dams are shown on Figure 1.

Access to Dams

The Cowpath Dam/Sullivan Dam facility is located approximately one-half mile north of Shelby along Business Route 15. Two gravel roads provide access to the dams from the highway.

Hazard Area

The evacuation area extends through the City of Shelby and along the unnamed tributary to the confluence with the Marias River approximately seven miles to the south, as shown in Appendix B. Hazards include the possible inundation of commercial and residential buildings, the railroad and State Highway 2. Inundation and evacuation maps are included in Appendix B.



COW PATH AND SULLIVAN DAMS
VICINITY MAP

FIGURE 1

HKA ASSOCIATES
ENGINEERS • PLANNERS
8M934.101 JULY 1991

Re

Responsibility and Authority

Pursuant to the Dam Safety Act, Chapter 15 of Title 85, MCA, the dam owner is responsible for production, coordination, maintenance, and implementation of this emergency action plan. The extent of owner implementation was defined through coordination of this plan with the Toole County Sheriff and the Disaster and Emergency Services (DES) coordinator.

Periodic Review/Update

The owner will review/update this EAP annually. Review/update by a qualified professional engineer will be accomplished as required by the dam's operating permit, but no less than every five years.

Approval

By my signature, I acknowledge that I, or my representative, have reviewed this plan and agree to the tasks and responsibilities assigned herein for my department and/or agency.

TOOLE COUNTY SHERIFF'S DEPT

DISASTER & EMERGENCY SERVICES

 11-02-2024

Signature

Date

Signature

Date

Responsibility and Authority

Pursuant to the Dam Safety Act, Chapter 15 of Title 85, MCA, the dam owner is responsible for production, coordination, maintenance, and implementation of this emergency action plan. The extent of owner implementation was defined through coordination of this plan with the Toole County Sheriff and the Disaster and Emergency Services (DES) coordinator.

Periodic Review/Update

The owner will review/update this EAP annually. Review/update by a qualified professional engineer will be accomplished as required by the dam's operating permit, but no less than every five years.

Approval

By my signature, I acknowledge that I, or my representative, have reviewed this plan and agree to the tasks and responsibilities assigned herein for my department and/or agency.

TOOLE COUNTY SHERIFF'S DEPT

DISASTER & EMERGENCY SERVICES



11/02/2021

Signature

Date

Signature

Date

NOTIFICATION PROCEDURES

Imminent or Actual Failure

If you reasonable believe a dam failure is imminent or likely to occur, begin the "Actual or Imminent Failure" warning procedure illustrated on Figure 2 (page 5). If you reasonably believe a failure is not imminent and not likely to occur, follow the "Potentially Hazardous Situation" procedure on Figure 3 (page 7).

It is very important that you give full weight to downstream public safety while deciding which procedure to follow. If Cowpath Dam and/or Sullivan Dam are failing, two things must be done immediately: (1) the hazard area downstream from the dam must be evacuated, and (2) any steps that might save the dam or reduce damage to the dam or hazard area downstream should be taken. (Refer to the map in Appendix B to determine the areas that are likely to be inundated if the dam fails). The evacuation should be initiated as shown in Figure 2.

It is the observer's responsibility to:

- a. Call the Emergency Services Dispatch Center (911) and Disaster and Emergency Services. Be sure to say, "This is an emergency." They will call other authorities and the media and begin the evacuation.
- b. Do whatever is necessary to bring anyone in immediate danger to safety. This includes someone on the dams, directly below the dams, or boating on the reservoir, or evacuees if so directed by the sheriff.
- c. Keep in frequent touch with the Sheriff's Office. They will tell you how to handle the emergency.
- d. If all means of communication are lost:
 - Try to find out why
 - Try to get to another radio or telephone that works
 - Get someone else to try to reestablish communications

If these means fail, handle the immediate problems as well as you can, and periodically try to reestablish contact with the Sheriff's Office. The Toole County Sheriff's Department will issue warnings to the general public in accordance with the Toole County Emergency Operations Plan.


Figure 2

COWPATH/SULLIVAN DAMS

ACTUAL OR IMMINENT FAILURE

NOTIFICATION FLOWCHART

NEAREST PHONES TO THE DAM ARE:



- 1/ If unable to reach Montana Department of Natural Resources in the event of an emergency, call Montana DES at 327-4777 and ask for the DES Duty Officer.

Potentially Hazardous Situation

A potentially hazardous situation is an event or condition not normally encountered in the routine operation of the dam and reservoir. Among the unusual occurrences that may affect the dam are embankment problems, failure of the spillways or outlet works, heavy precipitation or rapid spring snowmelt, landslides, earthquakes, erosion, theft, vandalism, acts of sabotage, and serious accidents. Potential problems, causes, consequences, and actions are presented in Appendix E. These occurrences may endanger the dam, the public, or the downstream valley and may necessitate a temporary or permanent revision of the dam's operating procedures. The City Superintendent or his designee will appropriately inspect and monitor conditions in response to unusual occurrences that may affect the dam's structures. Help in these situations can be obtained by notifying those people shown in Figure 3.

If the observer discovers an unusual condition of the dam embankment that could threaten the structure:

- a. Have a qualified engineer inspect the dam as soon as possible to determine whether emergency action is necessary
- b. Notify the Toole County Disaster and Emergency Services Coordinator of the potential problem.
- c. Contact Dam Safety Program of the Department of Natural Resources and Conservation.

When the City Superintendent calls either an engineer or the DNRC to report a problem, use the form in Appendix D to ensure you can provide sufficient information for the engineer to analyze the problems. In addition, prepare a sketch periodically if the problem develops further. The Manual for Operation and Maintenance of Dry Fork Dam includes further guidelines for courses of action to take to mitigate the effect of any problems. Continue to evaluate structure for failure and begin appropriate notifications if failure seems likely (see Figure 2).

Posting of the Notification Flowchart and Distribution of the Emergency Action Plan


The Notification Flowchart is posted at the dam and a copy of the EAP is in the City Hall. The Toole County Sheriff's Office and the Toole County DES Coordinator also have copies of the plan.

FIGURE 3

COWPATH/SULLIVAN DAMS

POTENTIALLY HAZARDOUS SITUATION

NOTIFICATION FLOWCHART



- 1/ Principal notification is noted by solid lines. If the first individual in a sequence is not contacted, Toole County Sheriff's Department will provide notification to those following.

MITIGATION ACTION

Besides normal monitoring of the dam's condition the owner will provide continuous monitoring and inspection during and after extreme events such as storms and earthquakes. Information on the magnitude of an earthquake or storm can be obtained from the DNRC Dam Safety Program. Actions are suggested to mitigate problems that may develop, but those actions should never be continued at the risk of injury or at the expense of lessening efforts related to evacuation.

POTENTIAL PROBLEMS AND IMMEDIATE RESPONSE ACTIONS

Potential problems, causes, consequences, and actions are presented in Appendix E.

EMERGENCY SUPPLIES AND RESOURCES

Soils suitable for emergency repairs are present in the original borrow areas used for construction of the facility. These areas are located at the west end of Sullivan Dam and on the southwest side of the connecting channel. Soils are also available at the City of Shelby landfill.

LOCAL CONTRACTORS

Shelby: Toole County Road Department 434-2742
Hiline Redi-Mix 434-5391

Conrad: Sullivan Brothers Construction 278-7940

Cut Bank: Alme Construction 873-4771

Sunburst: Pro Automotive 937-7400

ENGINEERS

Triple Tree Engineering, Helena, Montana 461-0692

APPENDIX A

TECHNICAL DATA FOR COWPATH DAM AND SULLIVAN DAM 1/

Maximum Reservoir Capacity to the

Crest of the Dam:	Cowpath: 940 acre feet
	Sullivan: 1,470 acre feet
	TOTAL (including connecting channel): 2,480 acre feet

Normal Reservoir Capacity Measured to the

Principal Spillway Crest:	Cowpath: 190 acre feet
	Sullivan: 360 acre feet
	TOTAL (including connecting channel): 553 acre feet

Normal Water Depth Measured from the Streambed

To the Crest of the Principal Spillway:	27 feet
---	---------

Dam Height Measured from the Streambed to the

Crest of the Dam:	49 feet
-------------------	---------

Dam Crest Width:	Cowpath: 18 feet
	Sullivan: 18 feet

Dam Width at Base:	Cowpath: 283 feet
	Sullivan: 283 feet

Length of Dam Crest:	Cowpath: 1,425 feet
	Sullivan: 750 feet

Outlet Capacity at Maximum Surcharge:	20 cubic feet per second
---------------------------------------	--------------------------

Principal Spillway Capacity at Maximum Surcharge:	35 cubic feet per second
---	--------------------------

Emergency Spillway Capacity at Maximum Surcharge:	3150 cubic feet per second
---	----------------------------

Date Constructed:	1967
-------------------	------

Slope of Upstream Face of Dam:


Cowpath: 3H:1V with a 10 feet wide berm at elev. 3341.0 feet MSL
Sullivan: 3H:1V with a 10 feet wide berm at elev. 3341.0 feet MSL

Slope of Downstream Face of Dam:

Cowpath: 2H:1V with a 10 feet wide berm at elev. 3341.0 feet MSL
Sullivan: 2H:1V with a 10 feet wide berm at elev. 3341.0 feet MSL

1/ CSSA. January 1980. Phase 1 Inspection Report, City of Shelby Watershed Dam

APPENDIX B



**COW PATH AND SULLIVAN DAMS
INUNDATION AND EVACUATION MAP**

APPENDIX B

**HKA ASSOCIATES
ENGINEERS • PLANNERS**
BMS34.101 NOV 91

APPENDIX C

TELEPHONE DIRECTORY

A. **Priority One**

- | | | |
|----|---|----------|
| 1. | ALL EMERGENCY SERVICES (24 HOURS) | 911 |
| 2. | TOOLE COUNTY DISASTER AND EMERGENCY SERVICES. | 450-8013 |
| | Coordinator: Kelsey Buckley | |
| | Montana Disaster and Emergency Services | |
| | Division (Helena) | 324-4777 |
| 3. | EVACUEES (in upstream-to-downstream sequence) | |
| | Clark, Casey | 450-3108 |
| | Pederson, Tammy. | 460-5331 |
| | Longcake, Bob | 434-5043 |

B. **Priority Two**

- | | | |
|----|--|-----------------|
| 4. | ENGINEERS | |
| | Triple Tree Engineering | 461-0692 |
| 5. | MONTANA DEPARTMENT OF NATURAL RESOURCES AND | |
| | CONSERVATION (DNRC) | |
| | Dam Safety Program Office . | 444-0862 |
| | Engineer: Michele Lemieux . . Office . | 444-6613 |
| | DNRC Havre Office: Office . | 265-5516 |
| 6. | NATIONAL WEATHER SERVICE | |
| | Great Falls | 453-2081 |
| 7. | OWNER AND OPERATOR OF COWPATH DAM & SULLIVAN DAM | |
| | Mayor: Gary McDermott . . . Office . | 434-5222 |
| | | Cell . 450-1173 |
| | Superintendent: Jack Johannes Office . | 434-5564 |
| | | Cell . 304-1307 |
| 8. | BUREAU OF LAND MANAGEMENT, Havre | 262-2820 |
| 9. | MONTANA DEPARTMENT OF STATE LANDS, Helena . . | 444-5499 |

APPENDIX D

DAM INCIDENT REPORT FORM

DATE _____ TIME _____ A.M./P.M.

NAME OF DAM _____

STREAM NAME _____

LOCATION _____

COUNTY _____

OBSERVER _____

OBSERVER TELEPHONE _____

NATURE OF PROBLEM _____

LOCATION OF PROBLEM AREA _____
(looking downstream)

EXTENT OF PROBLEM AREA _____

FLOW QUANTITY AND COLOR _____

WATER LEVEL IN RESERVOIR _____

IS SITUATION WORSENING? _____

EMERGENCY STATUS _____

CURRENT WEATHER CONDITIONS _____

ADDITIONAL COMMENTS _____


APPENDIX E

Potential Problems, Causes, Consequences and Action

PROBABLE CAUSE	POSSIBLE CONSEQUENCES	RECOMMENDED ACTIONS	
		HAZARDOUS	NON-HAZARDOUS
SINKHOLE	Piping or internal erosion of embankment materials or foundation causes a sinkhole. The cave-in of an eroded cavern can result in a sink hole. A small hole in the wall of an outlet pipe can develop a sink hole. Dirty water at the exit indicates erosion of the dam.	<p>HAZARDOUS Piping can erode a reservoir through a small hole in the wall or can lead to failure of a dam as soil pipes erode through the foundation or a pervious part of the dam.</p> <p>NON-HAZARDOUS Indicates onset of massive slide or settlement caused by foundation failure.</p>	<p>Inspect other parts of the dam for seepage or more sink holes. Identify exact cause of sink holes. Check seepage and leakage outflows for dirty water. A qualified engineer should inspect the conditions and recommend further actions to be taken. ENGINEER REQUIRED</p>
LARGE CRACKS	A portion of the embankment has moved because of loss of strength, or the foundation may have moved, causing embankment movement.	HAZARDOUS A series of slides can lead to obstruction of the outlet or failure of the dam.	NON-HAZARDOUS Evaluate extent of the slide. Monitor slide. (See Chapter 6.) Draw the reservoir level down if safety of dam is threatened. A qualified engineer should inspect the conditions and recommend further actions to be taken. ENGINEER REQUIRED
SLIDE, SLUMP OR SLIP	Earth or rocks move down the slope along a slipplane surface because of too steep slope, or the foundation moves. Also, look for slides movement in reservoir basin.	HAZARDOUS A series of slides can lead to obstruction of the outlet or failure of the dam.	NON-HAZARDOUS Erosion lessens the width and possible height of the embankment and could lead to increased seepage or overtopping of the dam.
SCARPS, BENCHES, OVERSTEEP AREAS	Wave action, local settlement, or ice action cause soil and rock to erode and slide to the lower part of the slope forming a bench.	HAZARDOUS Determine exact cause of scarp. Do necessary earthwork, restore embankment to original slope and provide adequate protection (bedding and riprap). See Chapter 7.	NON-HAZARDOUS Erosion lessens the width and possible height of the embankment and could lead to increased seepage or overtopping of the dam.

11 PROBLEM

BROKEN DOWN MISSING RIWRAP



PROBABLE CAUSE

Poor quality riprap has deteriorated. Wave action or ice action has displaced riprap. Round and similar-sized rocks have rolled downhill.


POSSIBLE CONSEQUENCES

Wave action against these unprotected areas decreases embankment width.

RECOMMEND ACTIONS

Re-establish normal slope. Place bedding and competent riprap. (See Chapter 7.)

EROSION BEHIND POORLY GRADED RIWRAP




Similar-sized rocks allow waves to pass between them and erode small gravel particles and soil.

Re-establish effective slope protection. Place bedding material. ENGINEER REQUIRED for design for gradation and size for rock for bedding and riprap. A qualified engineer should inspect the conditions and recommend further actions to be taken.

Figures 5.1.2 Inspection Guidelines - Downstream Slope

SLIDE/SLOUGH




1. Lack of or loss of strength of embankment material.
2. Loss of strength can be attributed to infiltration of water into the embankment or loss of support by the foundation.

HAZARDOUS
Massive slide cut through crest or upstream slope reducing freeboard and cross section. Structural collapse or overtopping can result.

1. Measure extent and displacement of slide.
2. If continued movement is seen, begin lowering water level until movement stops.
3. Have a qualified engineer inspect the condition and recommend further action.
ENGINEER REQUIRED

39. PROBLEM

TRANSVERSE CRACKING



PROBABLE CAUSE

Differential settlement of the embankment also leads to traverse cracking (e.g., center settles more than abutments).

POSSIBLE CONSEQUENCES


HAZARDOUS

Settlement or shrinkage cracks can lead to seepage of reservoir water through the dam. Shrinkage cracks allow water to enter the embankment. This promotes saturation and increases freeze-thaw action.

RECOMMENDED ACTIONS

1. If necessary, plug upstream end of crack to prevent flows from the reservoir.
2. A qualified engineer should inspect the conditions and recommend further actions to be taken.
ENGINEER REQUIRED

CAVE IN/COLLAPSE



1. Lack of adequate compaction.
2. Rooted hole below.
3. Piping through embankment or foundation.

HAZARDOUS
Indicates possible wash out of embankment.

1. Inspect for and immediately repair rodent holes. Control rodents to prevent future damage.
2. Have a qualified engineer inspect the condition and recommend further action.
ENGINEER REQUIRED

LONGITUDINAL CRACKING



1. Drying and shrinkage of surface material.
2. Downstream movement of settlement of embankment.

HAZARDOUS
Can be an early warning of a potential slide.

1. Shrinkage cracks allow water to enter the embankment and freezing will further crack the embankment.
2. If cracks are extensive, a qualified engineer should inspect the conditions and recommend further actions to be taken.
ENGINEER REQUIRED

SLUMP (LOCALIZED CONDITION)



Preceded by erosion undercutting a portion of the slope. Can also be found on steep slopes.


HAZARDOUS
Can expose impervious zone to erosion and lead to further slumps.

1. Inspect area for seepage.
2. Monitor for progressive failure.
3. Have a qualified engineer inspect the condition and recommend further action.
ENGINEER REQUIRED

PROBLEM

EROSION

Water from intense rainstorms or snowmelt carries surface material down the slope, resulting in continuous troughs.



PROBABLE CAUSE

RECOMMENDED ACTIONS

POSSIBLE CONSEQUENCES

Can be hazardous if allowed to continue. Erosion can lead to eventual deterioration of the downstream slope and failure of the structure.

1. The preferred method to protect eroded areas is rock or riprap.
2. Re-establish protective grasses can be adequate if the problem is detected early.

TREES/OBSCUARING BRUSH

Natural vegetation in area.


- Large tree roots can create seepage paths. Busted can obscure visual inspection and harbor rodents.
1. Remove all large, deep-rooted trees and shrubs on or near the embankment. Proper backfill void. (See Chapter 7.)
 2. Control vegetation on the embankment that obscures visual inspection. (See Chapter 7.)



RODENT ACTIVITY

Over-abundance of rodents. Holes, tunnels and caverns are caused by animal burrowing. Certain habitats like certain type plants and trees close to the reservoir encourage these animals.


1. Control rodents to prevent more damage.
2. Backfill existing rodent holes.
3. Remove rodents. Determine exact location of digging and extent of burrowing. Remove habitat and repair damages. (See Chapter 7.)



LIVESTOCK/CATTLE TRAFFIC

Excessive travel by livestock especially harmful to slope when wet.

1. Fence livestock outside embankment area.
2. Repair erosion protection, i.e., riprap, grass.




5.3 Figures 5.3.3
Inspection Guidelines •
Embankment Crest

PROBLEMS	PROBABLE CAUSE	POSSIBLE CONSEQUENCES	RECOMMENDED ACTIONS
LONGITUDINAL CRACK	<ul style="list-style-type: none"> 1. Uneven settlement between adjacent sections or zones within the embankment. 2. Foundation failure causing loss of support to embankment. 3. Initial stages of embankment slide. 	HAZARDOUS <ul style="list-style-type: none"> 1. Creates local area of low strength within embankment. Could be the point of initiation of future structural movement, deformation, or failure. 2. Provides entrance point for surface run-off into embankment, allowing saturation of adjacent embankment area, and possible lubrication which could lead to localized failure. 	<ol style="list-style-type: none"> 1. Inspect crack and carefully record location, length, depth, width, alignment, and other pertinent physical features. Immediately state out limits of cracking. Monitor frequently. 2. Engineer should determine cause of cracking and supervise steps necessary to reduce danger to dam and correct condition. 3. Effectively seal the cracks at the crest's surface to prevent infiltration by surface water. 4. Continue to routinely monitor crest for evidence of further cracking. <p>ENGINEER REQUIRED</p>
VERTICAL DISPLACEMENT	<ul style="list-style-type: none"> 1. Vertical movement between adjacent sections of the embankment. 2. Structural deformation or failure caused by structural stresses or instability, or by failure of the foundation. 	HAZARDOUS <ul style="list-style-type: none"> 1. Provides local area of low strength within embankment, which could cause future movement. 2. Leads to structural instability or failure. 3. Provides entrance point for surface water that could further lubricate failure plane. 4. Reduces available embankment cross section. 	<ol style="list-style-type: none"> 1. Carefully inspect displacement and record its location, vertical and horizontal displacement, length, and other physical features. Immediately stake out limits of cracking. 2. Engineer should determine cause of displacement and supervise all steps necessary to reduce danger to dam and correct condition. 3. Excavate area to the bottom of the displacement. Backfill excavation using competent material and correct construction techniques, and under supervision of engineer. 4. Continue to monitor areas routinely for evidence of future cracking or movement. (See Chapter 6.) <p>ENGINEER REQUIRED</p>
CAVE-IN ON CREST	<ul style="list-style-type: none"> 1. Rodent activity. 2. Hole in outlet conduit is causing erosion of embankment material. 3. Internal erosion or piping of embankment material by seepage. 4. Breakdown of dispersive clays within embankment by seepage waters. 	HAZARDOUS <ul style="list-style-type: none"> 1. Void within dam could cause localized caviting, sloughing, instability, or reduced embankment cross section. 2. Entrance point for surface water. 	<ol style="list-style-type: none"> 1. Carefully inspect and record location and physical characteristics (depth, width, length) of cave in. 2. Engineer should determine cause of cave in and supervise all steps necessary to reduce threat to dam and correct condition. 3. Excavate cave in, slope sides of excavation, and backfill hole with competent material using proper construction techniques. (See Chapter 7.) This should be supervised by engineer. <p>ENGINEER REQUIRED</p>

34. PROBLEM

TRANSVERSE CRACKING



PROBABLE CAUSE

1. Uneven movement between adjacent segments of the embankment.
2. Deformation caused by structural stress or instability.

POSSIBLE CONSEQUENCES

HAZARDOUS

1. Can provide a path for seepage through the embankment cross section.
2. Provides local area of low strength within embankment. Future structural movement, deformation or failure could begin.
3. Provides entrance point for surface runoff to enter embankment.

RECOMMENDED ACTIONS

1. Inspect crack and carefully record crack location, length, depth, width, and other pertinent physical features. Stake out limits of cracking.
 2. Engineer should determine cause of cracking and supervise all steps necessary to reduce danger to dam and correct condition.
 3. Excavate crest along crack to a point below the bottom of the crack. Then backfilling excavation using competent material and correct construction techniques. This will seal the crack against seepage and surface runoff. (See Chapter 7.) This should be supervised by engineer.
 4. Continue to monitor crest routinely for evidence of future cracking. (See Chapter 6.)
- ENGINEER REQUIRED

CREST MISALIGNMENT



1. Movement between adjacent parts of the structure.
2. Severe deflection of dam under loading by reservoir.
3. Structural deformation or failure near area of misalignment.

LOW AREA IN CREST OF DAM



1. Excessive settlement in the embankment or foundation directly beneath the low area in the crest.
2. Internal erosion of embankment material.
3. Foundation spreading to upstream and/or downstream direction.
4. Prolonged wind erosion of crest area.
5. Improper final grading following construction.

Reduces freeboard available to pass flood flows safely through spillway.

1. Establish monuments across crest to determine exact amount, location, and extent of misalignment.
 2. Engineer should determine cause of misalignment and supervise all steps necessary to reduce threat to dam and correct condition.
 3. Monitor crest monuments on a scheduled basis following remedial action to detect possible future movement. (See Chapter 6.)
- ENGINEER REQUIRED

37 PROBLEM



PROBABLE CAUSE

Neglect of dam and lack of proper maintenance procedures.


POSSIBLE CONSEQUENCES

1. Obscures large parts of the dam, preventing adequate, accurate visual inspection of all parts of the dam. Problems which threaten the integrity of the dam can develop and remain undetected until they progress to a point that threatens the dam's safety.
2. Associated root systems develop and penetrate into the dam's cross section. When the vegetation dies, the decaying root systems can provide paths for seepage. This reduces the effective seepage path through the embankment and could lead to possible piping situations.
3. Prevents easy access to all parts of the dam for operation, maintenance, and inspection.
4. Provides habitat for rodents.

RECOMMENDED ACTIONS

1. Remove all damaging growth from the dam. This would include removal of trees, bushes, brush, conifers, and growth other than grass. Grass should be encouraged on all segments of the dam to prevent erosion by surface runoff. Root systems should also be removed to the maximum practical extent. The void which results from removing the root system should be backfilled with wellcompacted, wellcompacted material.
2. Future undesirable growth should be removed by cutting or spraying, as part of an annual maintenance program. (See Chapter 7.)
3. All cutting or debris resulting from the vegetative removal should be immediately taken from the dam and properly disposed of outside the reservoir basin.

RODENT ACTIVITY



1. Completely backfill the hole with competent, wellcompacted material.
2. Initiate rodent control program to reduce the burrowing animal population and to prevent future damage to the dam. (See Chapter 7.)

BURROWING ANIMALS

1. Entrance point for surface runoff to enter dam. Could saturate adjacent portions of the dam.
2. Especially dangerous if hole penetrates dam below spillway line. During periods of high storage, seepage path through the dam would be greatly reduced and a piping situation could develop.

GULLY ON CREST



1. Can reduce available freeboard.
2. Reduces cross-sectional area of dam.
3. Inhibits access to all parts of the crest and dam.
4. Can result in a hazardous condition if due to overtopping.


HEAVY VEHICLE TRAFFIC

1. Poor grading X and improper detailing of crest, improper drains causes surface runoff to collect and drain of crest at low point in upstream or downstream shoulder.
2. Inadequate spillway capacity which has caused dam to overtop





1. Inhibits easy access to all parts of crest.
2. Allows continued development of rutting.
3. Allows standing water to collect and saturate crest of dam.
4. Operating and maintenance vehicles can get stuck.

RUTS ALONG CREST



1. Drain standing water from ruts.
2. Regrade and recompact crest to restore integrity and provide proper drainage to upstream slope. (See Chapter 7.)
3. Provide gravel or roadbase material to accommodate traffic.
4. Do periodic maintenance and regrading to prevent reformation of ruts.

14 PROBLEM	PROBABLE CAUSE	POSSIBLE CONSEQUENCES	RECOMMENDED ACTIONS
PUDDLING ON CREST - POOR DRAINAGE	1. Poor grading and improper drainage of crest. 2. Localized consolidation or settlement on crest allows puddles to develop.	1. Cause localized saturation of the crest. 2. Inhibits access to all parts of the dam and crest. 3. Becomes progressively worse if not corrected.	1. Drain standing water from puddles. 2. Reprade and recompact crest to restore integrity and provide proper drainage to upstream slope. (See Chapter 7.) 3. Provide gravel or roadway material to accommodate traffic. 4. Do periodic maintenance and regrading to prevent reformation of low areas.
DRYING CRACKS	Material on the crest of dam expands and contracts with alternate wetting and drying of weather cycles. Drying cracks are usually short, shallow, narrow, and many.	Provides point of entrance for surface runoff and surface moisture, causing saturation of adjacent embankment areas. This saturation, and later drying of the dam, could cause further cracking.	1. Seal surface of cracks with a light, impervious material. (See Chapter 7.) 2. Routinely grade crest to provide proper drainage and fill cracks. -OR- 3. Cover crest with non-plastic (not clay) material to prevent large moisture content variations.



39 Figures 5.3.4
Inspection Guidelines*
Embankment Seepage Areas

PROBLEM
**EXCESSIVE QUANTITY
AND/OR MUDDY WATER
EXITING FROM A POINT**



PROBABLE CAUSE

1. Water has created an open pathway, channel, or pipe through the dam. The water is eroding and carrying embankment material.
2. Large amounts of water have accumulated in the downstream slope. Water and embankment materials are cutting at one point. Surface agitation may be causing the muddy water.
3. Rodents, frost action or poor construction have allowed water to create an open pathway or pipe through the embankment.

POSSIBLE CONSEQUENCES

HAZARDOUS

1. Continued flows can saturate parts of the embankment and lead to slides in the area.
2. Continued flows can further erode embankment materials and lead to failure of the dam.

RECOMMENDED ACTIONS

1. Begin measuring outflow quantity and establishing whether water is getting muddier, staying the same, or clearing up.
 2. If quantity of flow is increasing the water level in the reservoir should be lowered until the flow stabilizes or stops.
 3. Search for opening on upstream side and plug if possible.
 4. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED**

**STREAM OF WATER
EXITING THROUGH CRACKS
NEAR THE CREST**



1. Severe drying has caused shrinkage of embankment material.
2. Settlement in the embankment or foundation is causing the transverse cracks.

1. Plug the upstream side of the crack to stop the flow.
2. The water level in the reservoir should be lowered until it is below the level of the cracks.
3. A qualified engineer should inspect the condition and recommend further actions to be taken.

**SEEPAGE WATER
EXITING AS A BOIL
IN THE FOUNDATION**



1. Some part of the foundation material is supplying a flow path. This could be caused by a sand or gravel layer in the foundation.

1. Examine the boil for transportation of foundation materials.
 2. If soil particles are moving downstream, sandbags or earth should be used to create a dike around the boil. The pressures created by the water level within the dike may control flow velocities and temporarily prevent further erosion.
 3. If erosion is becoming greater, the reservoir level should be lowered.
 4. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED**


40 PROBLEM

POSSIBLE CONSEQUENCES

RECOMMENDED ACTIONS

PROBABLE CAUSE

1. Water flowing through pathways in the abutment.
2. Water flowing through the embankment.




- HAZARDOUS**
Can lead to erosion of embankment materials and failure of the dam.

1. Study leakage area to determine quantity of flow and extent of saturation.
2. Inspect daily for developing slides.
3. Water level in reservoir may need to be lowered to assure the safety of the embankment.
4. A qualified engineer should inspect the conditions and recommend further actions to be taken.
ENGINEER REQUIRED

LARGE AREA WET OR PRODUCING FLOW

- A steppe path has developed through the abutment or embankment materials and failure of the dam can occur.



- HAZARDOUS**
Increased flows could lead to erosion of embankment material and failure of the dam.

1. Increased flows could lead to erosion of embankment material and failure of the dam.
2. Saturation of the embankment can lead to local slides which could cause failure of the dam.
3. Reservoir level may need to be lowered if saturated areas increase in size at a fixed storage level or if flow increases.
4. A qualified engineer should inspect the condition and recommend further actions to be taken.
ENGINEER REQUIRED

MARKE CHANGE IN VEGETATION

1. Embankment material are supplying flows path.
2. Natural seeding by wind.
3. Change in seed type during early post construction seeding.




- Can show a saturated area.

1. Stake out the saturated area and monitor for growth or thinning.
2. Measure any outflows as accurately as possible.
3. Reservoir level may need to be lowered if saturated areas increase in size at a fixed storage level or if flow increases.
4. A qualified engineer should inspect the condition and recommend further actions to be taken.
ENGINEER REQUIRED

BULGE IN LARGE WET AREA

- Downstream embankment materials have begun to move.



- HAZARDOUS**
Failure of the embankment result from massive sliding can follow these early movements.

1. Compare embankment cross section to the end of construction condition to see if observed condition may reflect end of construction.
2. Stake out affected area and accurately measure outflow.
3. A qualified engineer should inspect the condition and recommend further actions to be taken.
ENGINEER REQUIRED

4) PROBLEM




POSSIBLE CAUSE

1. Water moving rapidly through the embankment or foundation is being controlled or contained by a well-established turf root system.

RECOMMENDED ACTIONS

1. Carefully inspect the area for outflow quantity and any transported material.
 2. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED


LEAKAGE FROM ABUTMENTS BEYOND THE DAM



1. Water moving through cracks and fissures in the abutment materials.

1. Carefully inspect the area to determine quantity of flow and amount of transported material.
2. A qualified engineer or geologist should inspect the condition and recommend further actions to be taken.


WET AREA IN HORIZONTAL BAND



1. Wetting of areas below the area of excessive seepage can lead to localized instability of the embankment (SLIDES).

2. Excessive flows can lead to accelerated erosion of embankment materials and failure of the dam.
 3. Stake out the exact area involved.
 4. Using hand tools, try to identify the material allowing the flow.
 5. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED

LARGE INCREASE IN FLOW OR SEDIMENT IN DRAIN OUTFALL




1. A shortened, steeper path or increased storage levels.

1. Accurately measure outflow quantity and determine amount of increase over previous flow.
 2. Collect air samples to compare turbidity.
 3. If either quantity or turbidity has increased by 25%, a qualified engineer should evaluate the condition and recommend further actions.
- ENGINEER REQUIRED

42 Figures 5.4
Inspection Guidelines
Concrete Upstream Slope


PROBABLE CAUSE	POSSIBLE CONSEQUENCES	RECOMMENDED ACTIONS
CRACKED DETERIORATED CONCRETE FACE Concrete deteriorated resulting from weathering, joint filler deteriorated or displaced.	Soil is eroded behind the face and cavities can be formed. Unsupported sections of concrete crack. Ice action may displace concrete.	Determine cause. Either patch with grout or contact engineer for permanent repair method. 2. If damage is extensive, a qualified engineer should inspect the conditions and recommend further actions to be taken. ENGINEER REQUIRED



CRACKS DUE TO DRYING

The soil loses its moisture and shrinks, causing cracks. NOTE: Usually seen on crest and downstream slope mostly.


1. Monitor cracks for increases in width, depth, or length.
 2. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED



Figures 5.5
Inspection Guidelines •
Spillways

EXCESSIVE VEGETATION OR DEBRIS IN CHANNEL

1. Monitor cracks for increases in width, depth, or length.
 2. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED



1. Monitor cracks for increases in width, depth, or length.
 2. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED

Reduced discharge capacity; overflow of spillway; overtopping of dam. Prolonged overtopping can cause failure of the dam.

Clean out debris periodically; control vegetative growth in spillway channel. Install log boom in front of spillway entrance to intercept debris.

4 PROBLEM

EROSION CHANNELS




PROBABLE CAUSE

Surface runoff from intense rainstorms or flow from spillway carries surface material down the slope, resulting in continuous troughs. Livestock traffic creates gullies where flow concentrates water.

RECOMMENDED ACTIONS

Photograph condition. Repair damaged areas by replacing eroded material with compacted fill. Protect areas against future erosion by installing suitable rock riprap. Revegetate area if appropriate. Bring condition to the attention of the engineer during next inspection.

EXCESSIVE EROSION IN EARTH SLIDE CAUSES CONCENTRATED FLOWS



Unbated erosion can lead to slides, slumps or slips which can result in reduced spillway capacity. Inadequate spillway capacity can lead to embankment overtopping and result in dam failure.

Disturbed flow pattern; loss of material, increased sediment load downstream; collapse of banks; failure of spillway; can lead to rapid evacuation of the reservoir through the severely eroded spillway.


END OF SPILLWAY CHUTE UNDERCUT



Poor configuration of stilling basin area. Highly erodible materials. Absence of cutoff wall at end of chute.

Hazardous. Structural damage to spillway structure; collapse of slab and wall lead to costly repair.

WALL DISPLACEMENT



Poor workmanship; uneven settlement of foundation; excessive earth and water pressure; insufficient steel bar reinforcement of concrete.

Photograph condition. Repair damaged areas by replacing eroded material with compacted fill. Protect areas against future erosion by installing suitable rock riprap. Revegetate area if appropriate. Bring condition to the attention of the engineer during next inspection.

Minor displacement will create eddies and turbulence in the flow, causing erosion of the soil behind the wall. Major displacement will cause severe cracks and eventual failure of the structure.


Reconstruction should be done according to sound engineering practices. Foundation should be carefully prepared. Adequate weep holes should be installed to relieve water pressure behind wall. Use enough reinforcement in the concrete. Anchor walls to prevent further displacement. Install struts between spillway walls as needed. Clean out and backflush drains to assure proper operations. Consult an engineer before actions are taken.

ENGINEER REQUIRED

44 PROBLEM

POSSIBLE CAUSE

LARGE CRACKS



RECOMMENDED ACTIONS

HAZARDOUS
Disturbance in flow pattern; erosion of foundation and backfill; eventual collapse of structure.

LARGE CRACKS
Construction defect; local concentrated stress; local material deterioration; foundation failure, excessive backfill pressure.

Large cracks without large displacement should be repaired by patching. Surrounding areas should be cleaned or cut out before patching material is applied. (See Chapter 7.) Installation of weep holes or other actions may be needed.

OPEN OR DISPLACED JOINTS

Excessive and uneven settlement of foundations; sliding of concrete slabs; construction joint too wide and left unssealed. Sealant deteriorated and washed away.

HAZARDOUS
Erosion of foundation material may weaken support and cause further cracks; pressure induced by water flowing over displaced joints may wash away wall or slab, or cause extensive undermining.


Construction joint should be no wider than 1/2 inch. All joints should be sealed with asphalt or other flexible materials. Water stops should be used where feasible. Clean the joint, repair eroded materials, and seal the joint. Foundations should be properly drained and prepared. Underseals of chute slabs should have ribs of enough depth to prevent sliding. Avoid steep chute slope. **ENGINEER REQUIRED**

BREAKDOWN AND LOSS OF RIPRAP

Slope too steep; material poorly graded; failure of substrate; flow velocity too high; improper placement of material; bedding material or foundation washed away.

HAZARDOUS
Erosion of channel bottom and bank; failure of spillway.

Design a stable slope for channel bottom and banks. Riprap material should be well graded (the material should contain small, medium, and large particles). Sub-grade should be properly prepared before placement of riprap. Install filter fabric if necessary. Control flow velocity in the spillway by proper design. Riprap should be placed according to specification. Services of an engineer are recommended. **ENGINEER REQUIRED**




MATERIAL DETERIORATION, SPALLING AND DISINTEGRATION OF RIPRAP, CONCRETE, ETC.

Use of unsound or defective materials; structures subject to freeze-thaw cycles; improper maintenance practices; harmful chemicals.


Structure life will be shortened; premature failure.

Avoid using shale or sandstone for riprap. Add air entraining agent when mixing concrete. Use only clean good quality aggregates in the concrete. Steel bars should have at least 1 inch of concrete cover. Concrete should be kept wet and protected from freezing during curing. Timber should be treated before using.



45 PROBLEM

POOR SURFACE DRAINAGE



PROBABLE CAUSE

No weep holes; no drainage facility, plugged drains.


POSSIBLE CONSEQUENCES

Wet foundation has lower supporting capacity; uplift pressure resulting from a seepage water may cause damage to spillway chute; accumulation of water may also increase total pressure on spillway walls and cause damage.

RECOMMENDED ACTIONS

Install weep holes on spillway walls. Inner end of hole should be surrounded and packed with graded filtering material. Install drain system under spillway near downstream end. Clean out existing weep holes. Back-flush and rehabilitate drain system under the supervision of an engineer.
ENGINEER REQUIRED

CONCRETE EROSION, ABRASION, AND FRACTURING




Flow velocity too high (usually occurs at lower end of chute in high dam); rolling of gravel and rocks down the chute; cavity behind or below concrete slab.

Remove rocks and gravel from spillway chute before flood season. Raise water level in stilling basin. Use good quality concrete. Ensure concrete surface is smooth.
ENGINEER REQUIRED

LEAKAGE IN OR AROUND SPILLWAY

1. Cracks and joints in geologic formation at spillway are permitting seepage.
2. Gravel or sand layers at spillway are permitting seepage.




HAZARDOUS

1. Could lead to excessive loss of stored water.
2. Could lead to a progressive failure if velocities are high enough to cause erosion of natural materials.

1. Examine exit area to see if type of material can explain leakage.
2. Measure flow quantity and check for erosion of natural materials.
3. If flow rate or amount of eroded materials increases rapidly, reservoir level should be lowered until flow stabilizes or stops.
4. A qualified engineer should inspect the condition and recommend further actions to be taken.
ENGINEER REQUIRED

TOO MUCH LEAKAGE FROM SPILLWAY UNDER DRAINS



Drain or cutoff may have failed.


Same as above.

HAZARDOUS

1. Excessive flows under the spillway could lead to erosion of foundation material and collapse of parts of the spillway.
2. Uncontrolled flows could lead to loss of stored water.

44 PROBLEM

SEEPAGE FROM A CONSTRUCTION JOINT OR CRACK IN CONCRETE STRUCTURE



PROBABLE CAUSE

Water is collecting behind structure because of insufficient drainage or clogged weep holes.

POSSIBLE CONSEQUENCES

1. Can cause walls to tip in and over. Flows through concrete can lead to rapid deterioration from weathering.
2. If the spillway is located within the embankment, rapid erosion can lead to failure of the dam.

RECOMMENDED ACTIONS

1. Check area behind wall for puddling of surface water.
2. Check and clean as needed: drain outfalls, flush lines, and weep holes.
3. If condition persists a qualified engineer should inspect the condition and recommend further actions to be taken.

**Figures 5.6
Inspection Guidelines:
Inlets, Outlets and Drains
OUTLET PIPE DAMAGE**

CRACK



Settlement Impact

Rust (steel pipe)
Erosion (concrete pipe)
Cavitation

HAZARDOUS seepage, possible internal erosion.

HAZARDOUS
Excessive seepage, possible internal erosion.

Check for evidence of water either entering or exiting pipe at cracks/hole/etc.

Check for hollow sound which shows a void has formed along the outside of the conduit.

If a progressive failure is suspected, request engineering advice.

HAZARDOUS

Settlement or poor construction practice.

HAZARDOUS
Provides passageway for water to exit or enter pipe, resulting in erosion of internal materials of the dam.

Any of these conditions can mean the control system may bind. Control head works may set the gate may not open all the way. Support block may fail completely, leaving outlet inoperable.

HAZARDOUS

Cause control support block to tilt control stem may bind. Control head works may set the gate may not open all the way. Support block may fail completely, leaving outlet inoperable.

Outlet is inoperable.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem

Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

Bent. Excess force used to open or close gate. Inadequate or broken stem guides.

HAZARDOUS

Broken/missing stem guides

Loss of support for control stem. Stem may buckle and break under even normal use, (as in this example).

HAZARDOUS

Broken/missing stem


Rust. Inadequate lubrication. Excess force used to open or close gate when it was jammed.

HAZARDOUS

Bent/broken control stem

47 PROBLEM

FAILURE OF CONCRETE OUTFALL STRUCTURE



PROBABLE CAUSE

Excessive side pressures on noninforced concrete structure. Poor concrete quality.

POSSIBLE CONSEQUENCES

HAZARDOUS

Loss of outfall structure exposes embankment to erosion by outlet releases.

RECOMMENDED ACTIONS

1. Check for progressive failure by monitoring typical dimension, such as "D" shown in figure.
2. Repair by patching cracks and supplying drainage around concrete structure. Total replacement of outfall structure may be needed.

OUTLET RELEASES ERODING TOE OF DAM




Outlet pipe too short. Lack of energy-dissipating pool or structure at downstream end of conduit.

1. Extend pipe beyond toe (use a pipe of same size and material, and form watertight connection to existing conduit).
2. Protect embankment with trap over suitable bedding.

HAZARDOUS

Erosion of ice oversteeps downstream slope, causing progressive sloughing.

VALVE LEAKAGE DEBRIS STUCK UNDER GATE



Trashrack missing or damaged.

1. Raise and lower gate slowly until debris is located and floats past valve. When reservoir is lowered, repair or replace trashrack.

CRACKED GATE LEAF



Ice action, rust, affect vibration, or stress resulting from forcing gate closed when it is jammed.

1. Use valve only in fully open or closed position. Minimize use of valve until leaf can be repaired or replaced.

DAMAGE GATE SEAT OR GUIDES



Rust, erosion, cavitation, vibration, or wear.

1. Minimize use of valve until guides/seats can be repaired. If cavitation is the cause, check to see if air vent pipe exists and is unobstructed.

SEEPAGE WATER EXITING FROM A POINT ADJACENT TO THE OUTLET



1. A break in the outlet pipe.
2. A path for flow has developed along the outside of the outlet pipe.

1. Thoroughly investigate the area by probing and/or borelling to see if the cause can be determined.
 2. Determine if leakage water is carrying soil particles.
 3. Determine quantity of flow.
 4. If flow increases, or is carrying embankment materials, reservoir level should be lowered until leakage stops.
 5. A qualified engineer should inspect the condition and recommend further actions to be taken.
- ENGINEER REQUIRED

EMERGENCY ACTION PLAN

Names and Mailing Addresses

Gary McDermott, Mayor
City of Shelby
112 1st St S
Shelby, MT 59474

MT Disaster & Emergency
Services
1900 Williams St
Helena, MT 59602

Michele Lemieux
Dam Safety Program
Montana DNRC
PO Box 201601
Helena, MT 59620-1601

Toole County Sheriff
PO Box 550
Shelby, MT 59474

Kelsey Buckley
Toole County DES Coordinator
100 E Main St
Shelby, MT 59474

Jack Johannes
City Superintendent
City of Shelby
112 1st St S
Shelby, MT 59474

Montana Dam Safety Program
PO Box 202301
Helena, MT 59620-2301

Havre DNRC
PO Box 1828
Havre, MT 59501

Triple Tree Engineering
PO Box 162
Helena, MT 59624

National Weather Service
5324 Tri-Hill Frontage Rd
Great Falls, MT 59404-4933

High Hazard Dam Owner's Plan to Meet Engineer's Report Recommendations

*To be signed by dam owner and submitted to DNRC along with engineer's inspection report within 90 days of inspection.

Dam Name: Cowpath and Sullivan Inspection Date: 7/9/2021
Dam Owner: City of Shelby

Dam Inspection			
Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Monitor Erosion Areas Noted in Report - Upstream Left Groin - Sullivan - Downstream Abutment Groin - Sullivan - Upstream Face Right Groin - Cowpath - Downstream Face Left Groin - Cowpath - Upstream Abutment Left Groin - Cowpath	7/9/2022		
Periodic Removal of Debris from the Drop Structure	7/9/2022		
Ensure Toe Drain Outlet on Sullivan Dam is Unobstructed	7/9/2022		

**The engineer shall deliver the report and discuss it with the owner within 60 days of the investigation. (ARM36.14.603)
Within 90 days of the inspection, the owner shall deliver a copy of the report to the Department, together with a statement of the owner's intent in regard to any deficient or unsafe items identified by the report, and a time schedule to remedy the items. (ARM36.14.601)*

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>



Montana Water Resources Division

Dam Inspection

Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Consider Installing a Cap on the Threads at the Principal Spillway Gate	7/9/2022		
Cut or Spray Trees 6" or Smaller in Diameter from the Spillway Channel and Upstream Slope of Cowpath Dam	7/9/2022		
Clear Vegetation Away from Toe Drains on Cowpath Dam	7/9/2022		
Rodent Control	7/9/2022		

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>

Operation and Maintenance Manual Review

Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Annual Lubrication and Operation of the Principal Spillway Outlet Gate	7/9/2022		
Monitor Water Levels Below Primary Outlet Structure	7/9/2022		

Emergency Action Plan Review

Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
None, the EAP was updated on September 24, 2021.			

General Comments

By signing this document, you agree to diligently pursue remedies to your engineer's recommendations.

Signature – Dam Owner: _____ **Date:** _____

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>



The Montana Department of
Natural Resources
& Conservation



Montana Water Resources Division

High Hazard Dam Owner's Plan to Meet Engineer's Report Recommendations

*To be signed by dam owner and submitted to DNRC along with engineer's inspection report within 90 days of inspection.

Dam Name: Cowpath and Sullivan Inspection Date: 7/9/2021
Dam Owner: City of Shelby

Dam Inspection			
Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Monitor Erosion Areas Noted in Report - Upstream Left Groin - Sullivan - Downstream Abutment Groin - Sullivan - Upstream Face Right Groin - Cowpath - Downstream Face Left Groin - Cowpath - Upstream Abutment Left Groin - Cowpath	7/9/2022		
Periodic Removal of Debris from the Drop Structure	7/9/2022		
Ensure Toe Drain Outlet on Sullivan Dam is Unobstructed	7/9/2022		

**The engineer shall deliver the report and discuss it with the owner within 60 days of the investigation. (ARM36.14.603)
Within 90 days of the inspection, the owner shall deliver a copy of the report to the Department, together with a statement of the owner's intent in regard to any deficient or unsafe items identified by the report, and a time schedule to remedy the items. (ARM36.14.601)*

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>



Dam Inspection			
Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Consider Installing a Cap on the Threads at the Principal Spillway Gate	7/9/2022		
Cut or Spray Trees 6" or Smaller in Diameter from the Spillway Channel and Upstream Slope of Cowpath Dam	7/9/2022		
Clear Vegetation Away from Toe Drains on Cowpath Dam	7/9/2022		
Rodent Control	7/9/2022		

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>



Operation and Maintenance Manual Review

Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
Annual Lubrication and Operation of the Principal Spillway Outlet Gate	7/9/2022		
Monitor Water Levels Below Primary Outlet Structure	7/9/2022		

Emergency Action Plan Review

Engineer's Recommendation	Recommended Completion Date	Owner's Plan to Address Engineer's Recommendation	Date to be Completed
None, the EAP was updated on September 24, 2021.			

General Comments

By signing this document, you agree to diligently pursue remedies to your engineer's recommendations.

Signature – Dam Owner:

Date: 10/1/21

<http://dnrc.mt.gov/divisions/water/operations/dam-safety>



The Montana Department of
Natural Resources
& Conservation

